



Service Bulletin

Bulletin No.: 21-NA-263

Date: November, 2021

INFORMATION

Subject: Information for Police Tahoes that were Ordered Without Flashing Headlamps and Taillamps

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Tahoe	2021	2022	-	-	-	-

Involved Region or Country	North America
Additional Options (RPOs)	Equipped with FLASHER-HEADLAMP (SEO) (RPO 6J7)
Condition	The purpose of this bulletin is to notify dealership personal that some 2021–2022 Tahoes were ordered without RPO 6J7 which provides the flashing headlamps and taillamps.
Cause	This may be due to some confusion on which other calibrations need to be added to provide RPO 5J9 Red/White flashing taillamps or RPO 5L0 Red/Red flashing taillamps.
Correction	Technicians need to inform the Techline consultant that they need to add RPO 6J7 to the BCM and either RPO 5J9 or RPO 5L0 to the Electronic Lighting Module (ELM).

Warranty Information

This is a customer pay modification and subject to a single reconfiguration fee.

Version	1
Modified	Released November 17, 2021

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION